

Link do produktu: <https://www.pilarz.net.pl/linka-hamulca-partner-p53-550cm-p4053-p4553-cm-cmh-p-193.html>



## Linka hamulca partner P53-550CM P4053 P4553 CM CMH

Cena	<b>23,00 zł</b>
Dostępność	<b>Dostępny</b>
Czas wysyłki	<b>24 godziny</b>
Numer katalogowy	<b>470040</b>
Kod producenta	<b>470040</b>

### Opis produktu

Wysokiej jakości zamiennik stosowany w naszym serwisie.

Pasują do:

**Husqvarna:** 5321765-56;532 17 65-56

**Długość pancierza** - 1150 mm

**Długość linki** - 1320 mm

Modele:

#### **Partner**

P53-550CM

P4053 CM

P4553 CMH

P4553 CM

#### **MCCULLOCH**

M53-550 CM

MM4053 CM

M4553 CM

#### **AYP**

PO500N21R, PR160N21CHC,

PR4N22SHA, PR550N21RH3, WM500N21R

XT625N21RN3

#### **Husqvarna**

5521 CM (96133000300) (2006-04) Walk Mower

5521 CM (96133000301) (2006-08) Walk Mower

---

5521 CM (96133000302) (2006-12) Walk Mower  
5521 CM (96133000303) (2007-04) Walk Mower  
5521 CM (96133000304) (2007-04) Walk Mower  
5521 CM (96133000305) (2008-01) Walk Mower  
5521 CM (96133000306) Walk Mower  
5521 CMA (954223487) (2002-11) Walk Mower  
7021 CM (96133000100) (2004-10) Lawn Mower  
7021 CMA (954224088) (2003-11) Lawn Mower  
7021 CMB (954224088) (2004-01) Lawn Mower  
7021 CMC (954224088) (2004-09) Lawn Mower  
7021 CP (96133000200) (2005-01) Lawn Mower

**Weed Eater**

961140007 (2007) Walk Behind Lawn Mower  
961140007 (2008) Walk Behind Lawn Mower  
96114000800 Walk Behind Lawn Mower  
96114001404 Walk Behind Lawn Mower  
96134000106 Walk Behind Lawn Mower  
96134000301 Walk Behind Lawn Mower  
96134000600 Walk Behind Lawn Mower  
CHD4QE22SB Walk Behind Lawn Mower  
WE300N20S Walk Behind Lawn Mower  
WM5N22SHA Rotary Lawn Mower  
96116000100 Gas Rotary Lawn Mower  
WM45N22SA Rotary Lawn Mower

**Poulan**

PO450N20S (430499) Lawn Mower  
CH65N21RH Rotary Lawn Mower  
96136000100 Rotary Lawn Mower  
96134000800 Lawn Mower